



VOIDDOM

instrucciones de montaje/assembly instructions

Ref. 54044 / 54045




x1



54044

x1



54045

x1



x4



x4



x4



x1



En todos los set de montaje se suministra una llave Torx T25 para atornillar
Torx T25 spanner is included in each set

